



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 6
1445 ROSS AVENUE, SUITE 1200
DALLAS TX 75202-2733

Via FedEx

APR 14 2010

Eric F. Pastor
Pastor, Behling & Wheeler, LLC
2201 Double Creek Drive, Suite 4004
Round Rock, TX 78664

Re: Gulfco Marine Maintenance Superfund Site, Freeport, Texas
Unilateral Administrative Order, CERCLA Docket No. 06-05-05A
Draft Baseline Ecological Risk Assessment Problem Formulation and Work Plan
& Sampling and Analysis Plan

Dear Mr. Pastor,

The Environmental Protection Agency (EPA) and the Texas Commission on Environmental Quality (TCEQ) have performed a review of the above referenced documents dated March 10, 2010. The enclosed comments shall be incorporated in the final Problem Formulation and the final Work Plan & Sampling and Analysis Plan, and copies provided to the notification list within twenty-five (25) days of receipt of this letter.

If you have any questions, please contact me at (214) 665-8318, or send an e-mail message to miller.garyg@epa.gov.

Sincerely yours,

Gary Miller, P.E.
Remediation Project Manager

Enclosure

cc: Luda Voskov (TCEQ)
Susan Roddy
Barbara Nann



886244